12th permit :-

A. N. CHOWDHARY, M.Sc.,
GEOLOGIST

Phone :
Cell : 98454 73398

SRI SHIRDI SAI CONSULTANTS

10, 3rd Floor, 19th Cross, 14th Main, Revenue Layout, Padamanabhanagar
Bangalore - 560 061.

GROUND WATER INVESTIGATION REPORT

To the Asst Executive Engineer -
BBMP
Dasarahalli Zone Division -
Mahadeshwaraswamy Temple Road -

S. No. :

Date : 26.5.2014

1. Name of the Customer
2. a) Village Ward No:- 14 near Bhrmasamaja mandira b) Block / Taluk. c) District Bangalore
3. Location.
4. Lithology of the Area Granetic / Schistic in nature
5. Tophographic Features of the Area The area was a plain land
6. Hydrogeological condition of the Area Both -
7. Geophysical survey result. By Diving method
   a) Type of Method.
   b) No of Soundings Conducted.
   c) Recommended Sounding.
   d) Particulars of formations present in the subsurface/possible ground water zones encountered at
      - Around 60c'g
      - 850 - 880'
      - 1050 - 1080'
      } 2
   e) Condition of Ground Water.
8. Type of well Recommended. Both
9. Depth Recommended. Bore well (6½") -
10. Expected Yield. 1050 - 1100' 1600 - 1800 GPH -
11. Approximate depth at which the water is expected to be met. Good -
12. Recommended Type and Length of casing to be inserted. Around 60c'g
13. Rain water Harvesting adviced or not nearly 100 - 110 g MS casing may be needed -
14. Remarks. Strictly Adviced -

Recommended point for Drilling

Bhrmasamaja mandira

Not to scale

Site Plan Map

Signature of the consultant

Note :- The Survey was carried out by this divining / Geophysical method of surveying is with our good knowledge and experience. However no guarantee of water will be given.

6th permit :-

A. N. CHOWDHARY, M.Sc.,
GEOLOGIST

Phone :
Cell : 98454 73398

SRI SHIRDI SAI CONSULTANTS

10, 3rd Floor, 19th Cross, 14th Main, Revenue Layout, Padamanabhanagar
Bangalore - 560 061.

GROUND WATER INVESTIGATION REPORT

To the Assistant Executive Engineer
BBMP
Dasarahalli Sub Division
Sampigehalli Railway cross

S. No. :

Date : 26.5.2014

1. Name of the Customer
2. a) Village Ward No:- 14 6th cross Road b) Block / Taluk. c) District Bangalore
3. Location.
4. Lithology of the Area Granetic / Schistose in nature
5. Tophographic Features of the Area The area was a plain area
6. Hydrogeological condition of the Area Belt
7. Geophysical survey result. By Diving method
   a) Type of Method.
   b) No of Soundings Conducted.
   c) Recommended Sounding.
   d) Particulars of formations present in the subsurface/possible ground water zones encountered at
      750 - 800' }
      1020 - 1050' } = 2
   e) Condition of Ground Water.
8. Type of well Recommended. Bore well ($6\frac{1}{2}$")
9. Depth Recommended. 1000 - 1050'
10. Quality of Water. 1000 - 1600 GPH Good
11. Approximate depth at which the water is expected to be met. Around 750'
12. Recommended Type and Length of casing to be inserted. Around 140 - 160' M.S Casing may be needed
13. Rain water Harvesting adviced or not Strictly Adviced
14. Remarks.

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಜಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಬಾಗಲಗುಂಟೆ, ಬೆಂಗಳೂರು - 560 073

Need Recommended permit for Drilling

6th Cross Road

Site Plan Map

Not to scale

Signature of the consultant

ನೀರು ಅಮೂಲ್ಯ, ಅದನ್ನು ಸಂರಕ್ಷಿಸಿ
"WATER IS PRECIOUS, CONSERVE IT"

Note :- The Survey was carried out by this divining / Geophysical method of surveying is with our good knowledge and experience. However no guarantee of water will be given.

PALLAVI BOREWELL & DRILLERS

Dealers in : 6½" 4½" Borewells Drilling & Inwell Drilling
All Kinds of Motors & Pumps, Sales & Service
No. 66/8, 1st Main Road, Maruthi Layout, M. G. Road,
Nelamangala Bangalore - 562 123.
Moble : 93412 24311, 90089 87530,



Ref : *Date :* 30.6.2014

YIELD REPORT

1. Name and Address of the Party : AEE Ward No 73 Dasarahalli Sub Division
2. Borewell Location : Manakeshi Layout
3. Total Depth Drilled : 1049 Feet
4. Casing Pipe : 118 Feet
5. Coupling : 3 Coupling
6. Yield Details :
   a) First Spring Touched at : 360 Feet
   b) Second Spring Touched at : 590 Feet
   c) Third Spring Touched at : 910 Feet
7. Total Yield in G.P.H. : 1200 GPH
8. Remarks : Yield is Good

ok

ಮಹಾಲಿಪಿಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಧಿಕಾರಿ
ಆ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಬಾಗಲಗುಂಟೆ. ಬೆಂಗಳೂರು - 560 073

For PALLAVI BOREWELL & DRILLERS

M B Srinivasamurthy

Proprietor

PALLAVI BOREWELL & DRILLERS

Dealers in : 6½" 4½" Borewells Drilling & Inwell Drilling
All Kinds of Motors & Pumps, Sales & Service

No. 66/8, 1st Main Road, Maruthi Layout, M. G. Road,
Nelamangala Bangalore - 562 123.
Moble : 93412 24311, 90089 87530,



Ref : *Date :* ..30.6.2014.....

YIELD REPORT

1. Name and Address of the Party : ATE ward No. 14 Dasarahalli Sub station
2. Borewell Location : Sampigeriam layout
3. Total Depth Drilled : 1049 Feet
4. Casing Pipe : 118 Feet
5. Coupling : 3 couplings
6. Yield Details :
   a) First Spring Touched at : 453 Feet
   b) Second Spring Touched at : 780 Feet
   c) Third Spring Touched at : 915 Feet
7. Total Yield in G.P.H. : 1200 GPH
8. Remarks : Efficient Good

ಕಂದಾಯ ಮಾಹಿತಿ ಕೇಂದ್ರ ಉಪ ನೋಂದಣಿ
ಶ್ರೀ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಜಾಲಹಳ್ಳಿ, ಬೆಂಗಳೂರು - 560 073

For PALLAVI BOREWELL & DRILLERS

Proprietor